

# Sunday Hot Farm Tractor

## Open Speed

20 inch drawbar height

### Weight Class

9500, 11000, 13000

1. **Wide fronts and fenders required. Diesel fuel only**
2. **3000 RPM Max - RPMs checked by photo cell tack before or after hook. All tractors must have a positive throttle stop at the injection pump.**
3. **Cut tires allowed. Radials allowed. 18.4-38, 20.8-38, or 18.4-42**
4. **20" drawbar with 3" opening.**
5. **Fire extinguisher.**
6. **Wheelie bars must be able to support the weight of the tractor and no more than 10" inches above ground, bars should extend 3" inches or more from the furthest rear radius point of the tire.**
7. **Flywheel cover-blanket or 6" x 3/8" steel.**
8. **Kill switch-Diesel tractors; air shut off.**
9. **Dead man throttle.**
10. **Engine side shields.**

### Safety Equipment Recommended

Electric fan

Steel Flywheels

Frame tie bars

Roll bars

**General rules apply to all pullers and track judges will have the final decision.**

# Sunday Hot Farm Tractor

## Open Speed

20 inch drawbar height

Weight Class  
5500, 6500, 7500

1. Naturally aspirated Gas or Diesel only.
2. 20 inch draw bar rule with 3" inch opening.
3. 18.4-38 max tire footprint. Cut tires allowed.
4. Rpm unlimited, 3000 RPM above requires safety equipment.
5. Rear Fender Required
6. Flywheel cover- Blanket or 6" x 3/8" steel.
7. Engine side shields.
8. Dead Man Throttle.
9. Kill Switch.
10. Wheelie Bars must be able to support the weight of the tractor and no more than 10" inches above ground, bars should extend 3" inches or more from the furthest rear radius point of the tire.
11. Steel shield around fan.

### Safety Equipment Recommended

Electric fan  
Steel Flywheels  
Frame tie bars  
Roll bars

**General rules apply to all pullers and track judges will have the final decision.**